# *Pairing with Pairing button on SD1000.

| Master Device | LED Status | Slave Device | LED Status |
|---|---|---|---|
| 1 Push the Reset button for 3 sec. | Mode Led On | | |
| | | 2 Push the Reset button for 3 sec on Slave#1. | Mode Led On |
| | | 3 Push the Pairing button for 3 sec on Slave#1. | Mode Led Blinking (3 times per 1sec) |
| 4 Push the Pairing button for 3 sec. | Mode Led Blinking (3 times per 1sec) | | |
| 5. Again push the Pairing button for 3 sec | Mode Led Blinking (1 time per 1sec) | | |
| Connect with Slave#1 | Connect Led Blinking | Connect with Master | Connect Led Blinking |
| 6 Push the Pairing button for 3 sec. | Mode Led Blinking (1 time per 1sec) | | |
| (Into the Multiple connection mode) | Mode Led On Connect Led Blinking | | Connect Led Blinking |
| | | 7 Push the Reset button for 3 sec on Slave#2. | Mode Led On |
| | | 8 Push the Pairing button for 3 sec on Slave#2. | Mode Led Blinking (3 times per 1sec) |
| 9 Push the Pairing button for 3 sec | Connect Led Blinking | | |
| Connect with Slave#2 | Mode Led On Connect Led Blinking | Connect with Master | Connect Led Blinking |
| | | 10 Push the Reset button for 3 sec on Slave#3. | Mode Led On |
| | | 11 Push the Pairing button for 3 sec on Slave#3. | Mode Led Blinking (3 times per 1sec) |
| 12 Push the Pairing button for 3 sec | Mode Led Blinking (1 time per 1sec) | | |
| Connect with Slave#3 | Mode Led On Connect Led Blinking | Connect with Master | Connect Led Blinking |
| | | 13 Push the Reset button for 3 sec on Slave#4. | Mode Led On |
| | | 14 Push the Pairing button for 3 sec on | Mode Led Blinking (3 times per 1sec) |

| | | Slave#4. | |
|---|---|---|---|
| 15 Push the Pairing button for 3 sec | Mode Led Blinking (1 time per 1sec) | | |
| Connect with Slave#4 | Mode Led On Connect Led Blinking | Connect with Master | Connect Led Blinking |